ASSEMBLY INSTRUCTIONS

CH56

List of parts

No.	Description	Pcs
A		1
B		1

List of hardware

No.	Description	Qty
a	M6*20	4
b	M6*16	4
c		1

step1